Bypass Local

Waybills: Yes

Expiration Date: 04-22-2020

Include All Empty Cars: No

Tier 2 Effective Date: 04-22-2019

Issuing Road: DSRC - DAKOTA SOUTHERN RAILWAY COMPANY

Email: wendallhoffman@dakotasouthern.com

Email: wendallhoffman@dakotasouthern.com



Home Embargoes OPSL Notes Help

Embargo Details

General Embargo Information

Embargo No: DSRC000219

Effective Date: 04-22-2019

Status: Effective

Allow Permits: Yes

Include Empty Revenue Cars: No

Permit Officer: Wendall Hoffman

Original Requester: Wendall Hoffman Roads Invited to Participate: BNSF

Commodity

Target All Commodities

Cause

Cause:

Weather Conditions - specify

Cause Detail: Freeze/thaw cycle, high water causing impassable surface conditions resulting in a

service shut down.

Geography

Include These Locations: ORIGIN		Bi-Directional			DESTINATION		
Roadmark FSAC	Station Name	State/Province	Y	Roadmark DSRC	FSAC	Station Name	State/Province SD
Exclude These Locations:							

Amendment No.: 3

Max Car Allowed:

Effective Immediately: Yes

Phone Number: 605-682-8346

Phone Number: 605-682-8346

Exclude These Locations.	ORIGIN		Bi-Directional			DESTINATION	2
Roadmark FSAC	Station Name	State/Province	~	Roadmark	FSAC 03740	Station Name	State/Province
<u> </u>			•		03750	TITTERTON SDG	SD

Equipment

UMLER Equipment Types: Target All UMLER Equipment Types

Total Weight on Rail: No Weight Restrictions

Clearance Code: No Clearance Code

Waybill Parties

Target All Waybill Parties Amendment History

Amenume	all history					
Amendme	nt No. Amendment Date/Time	Amendment Reason	Amendment Reason Detail		Roadmark	Officer
3 (Curren	t) 05/09/2019 17:41:40	Other-Specify	Modified embargoed territory, added Kimball. Track conditions due to recent rains	have deteriorated.	DSRC	DSRCWH
2	05/03/2019 21:16:25	Other-Specify	Allow empty cars to move without a permit.		DSRC	DSRCWH
1	04/24/2019 17:54:37	Other-Specify	Track returned to service on the eastern portion of out-of service track.		DSRC	DSRCWH

Printable View

Return